




SUBMITTING CLEAR AND CORRECT PICTURES IS FUNDAMENTAL FOR US TO UNDERSTAND AND IDENTIFY THE BEST POSSIBLE FITTING FOR YOUR HELMET.

PLEASE TAKE YOUR TIME AND ASK SOMEONE FOR HELP (PLEASE DO NOT DO IT YOURSELF AND ASK FOR ASSISTANCE, FOR BOTH MEASURING AND FOR TAKING PICTURES. PICTURES MUST BE HIGH QUALITY AND 300DPI MINIMUM)

ANY ORDER WITH PHOTOS THAT DON'T MEET OUR STANDARDS WILL NOT BE ACCEPTED

MEASUREMENT N.1 - HEAD CIRCUMFERENCE




Measure the circumference of the head at the forehead height, being careful that the tape is placed horizontally and has the right tension (not too loose, not too tight)

The angle of the picture MUST BE EXACTLY as shown and the size on the measuring tape MUST be READABLE as per guide picture

SIZE MUST BE READABLE

MEASUREMENT N.2 - FACE CIRCUMFERENCE




Extend the tape measure around the face, being careful it sits on the TIP of the chin, right above the ears and up to the top back of the head.

The angle of the picture MUST BE EXACTLY as shown and the size on the measuring tape MUST be READABLE as per guide picture. Please keep the tape at the right tension.

SIZE MUST BE READABLE

MEASUREMENT N.3 - FACE WIDTH



Position 2 rulers (or similar objects) on the cheeks starting at the base of the ears, EXACTLY AS PER PICTURES. RULERS MUST BE HELD VERTICALLY AND PARALLEL. ASK SOMEONE TO Extend the tape horizontally and measure the distance between the 2 points.

NOTE:
A THIRD PERSON SHOULD BE TAKING THE PICTURE.

SIZE MUST BE READABLE



The angle of both pictures MUST BE EXACTLY as shown and the size on the measuring tape MUST be READABLE as per guide picture. Please keep the tape at the right tension.